



Date: 24.02.2024

Model: Emira 2023/24 Selected  
Model Year VIN Range

Number: 131-24003  
USA Market

Copy files should be maintained by:

Service Manager		Service Reception		Supervisor		Parts Manager	
-----------------	--	-------------------	--	------------	--	---------------	--

#### TITLE

Installation of the latest ECM software for Emira vehicles in the Federal market to ensure that they meet the current CARB compliance requirements.

#### REASON

This latest level ECM program **MUST** be installed into the affected vehicles as soon as possible.

#### ECM Software Part Numbers

Old Part number: V6 J1U3 → New Part number: V6 J1U4 Description: ECM SW

#### IMPORTANT

**To receive CARB (California Air Resources Board) certification, affected stock and inventory vehicles MUST have their ECM software updated before March 11th 2024. Vehicles CANNOT be retained until Lotus informs the dealer network that CARB approval has been granted.**

#### ACTION

- Check and identify any affected Emira vehicles from your inventory stock, dealer demonstrators to ensure that this campaign action is performed at the first opportunity.
- Any affected stock vehicles must be retained at the dealership until the actions as instructed in this bulletin are performed. Even once the retail embargo is lifted, it is essential that you do not deliver any affected vehicles until Lotus informs the dealer network that CARB approval has been granted.
- At the time of bulletin release, this campaign action is not displayed on the Lotus Dealer Connect warranty system, but a list of affected VINs in model year serial number sequential order is shown from page 4 of this bulletin. Please perform the ECM update as described in this bulletin immediately and a further communication will be sent when campaign number (TSB-132-24003) is available on warranty option DC611.

#### Procedure

##### *Preparation:*

Using the Lotus Insight tool, the Emira Diagnostic System will show the availability of a new software version for the ECM. Also ensure that the required prerequisites are fulfilled for the Diagnostic System, see next page for further information.

#### IMPORTANT

Before updating the ECM software, ensure to check if the vehicle also requires a VDDM software update, (see Technical Service Bulletin TSB-131-24002).


If a VDDM update is also required, then it is **essential** that this is performed first to avoid the possibility of the VDDM 'going to sleep' during the ECM software update procedure and potentially disabling the vehicle.

Continued..



### Checking the ECM Software is the Latest Level

1. Locate the Engine Control Module as shown in the image.



2. Select the ECM update under the software menu, if the latest ECM software is already installed, then see inspection type 1 in the warranty charges section of this bulletin.

3. If the latest ECM software is not installed, follow the instructions provided on the screen to complete the update

### Diagnostic System Prerequisites and Information

1. When presented with an available software update for ECM select the module to review any additional information.
2. Select RELOAD to carry out a software reload.
3. The download requirements may present additional messages as part of the process, please review these prior to commencing the download, ALWAYS READ AND COMPLY WITH THE PRE-REQUISITES.
4. Always ensure the preconditions are met to avoid failed software programming. Prior to any software update, check that any and all Windows system updates are installed in the Lotus Insight Tool (DO NOT UPGRADE TO WINDOWS 11) and to connect to a power supply to avoid unwanted shutdown. Other requirements include connecting a battery charger to maintain the vehicle 12 Volt battery, connection to a stable WiFi network and to check the vehicle is in Active mode (i.e. ignition is ON). If the battery voltage is insufficient, even while on a battery charger, Software download will not commence.
5. Ensure a suitably capable vehicle 12V battery charger is connected AND switched on prior to commencing download.
6. ENSURE WIFI CONNECTION IS STABLE AND NOT INTERRUPTED – a poor WiFi connection will slow down software download.
7. Ensure Lotus Insight Tool is powered during download, (the settings can be configured never to sleep when on battery or when power plugged in).
8. Take care not to disturb the VCI connection to the vehicle or USB connection to Insight Tool to prevent failed software download.
9. Always press UPLOAD LOGS before starting any software download.
10. After software download is completed, it may be necessary to carry out a battery disconnect to reset the vehicle. If you experience a failure to start engine/put vehicle into ACTIVE mode, then this will be required anyway.
11. Software part numbers will be updated in the Lotus data systems following successful update. The upgrade option will then disappear from the menu.

### Group Lotus

47584 Galleon Dr, Plymouth, Michigan 48170, United States



Bulletin number 131-24003  
USA market  
continued page 3

### CHARGES

When the campaign becomes available on the Lotus Dealer Connect warranty system, Use the applicable inspection type shown below, submit a warranty claim from option DC603, Bulk Entry Campaign, entering campaign number TSB-131-24003.

**Inspection Type 1:** Check ECM software level, already updated: 0.1 hours/vehicle.

**Inspection Type 2:** Update ECM software level: 0.3 hours/vehicle.

Note: All software downloads are recorded by the Emira Diagnostic System and are periodically checked by Lotus as part of the warranty auditing procedure.

Ends.



VINS AFFECTED BY TSB-131-24003

SCCLEKAX2PHA24352	SCCLEKAX3RHA10463	SCCLEKAX4RHA10522	SCCLEKAX7RHA10580
SCCLEKAX4RHA10231	SCCLEKAX1RHB10464	SCCLEKAX2RHB10523	SCCLEKAX9RHA10581
SCCLEKAX1RHB10366	SCCLEKAX9RHA10466	SCCLEKAX8RHA10524	SCCLEKAX0RHA10582
SCCLEKAX6RHA10408	SCCLEKAX7RHB10467	SCCLEKAXXRHA10525	SCCLEKAX2RHA10583
SCCLEKAX8RHA10409	SCCLEKAX2RHA10468	SCCLEKAX1RHA10526	SCCLEKAX4RHA10584
SCCLEKAX4RHA10410	SCCLEKAX4RHA10469	SCCLEKAXXRHB10527	SCCLEKAX2RHB10585
SCCLEKAX2RHB10411	SCCLEKAX7RHB10470	SCCLEKAX5RHA10528	SCCLEKAX8RHA10586
SCCLEKAX8RHA10412	SCCLEKAX9RHB10471	SCCLEKAX3RHB10529	SCCLEKAX6RHB10587
SCCLEKAX6RHB10413	SCCLEKAX0RHB10472	SCCLEKAX3RHA10530	SCCLEKAX8RHB10588
SCCLEKAX1RHA10414	SCCLEKAX2RHB10473	SCCLEKAX5RHA10531	SCCLEKAX3RHA10589
SCCLEKAX3RHA10415	SCCLEKAX8RHA10474	SCCLEKAX3RHB10532	SCCLEKAX4RHA10598
SCCLEKAX1RHB10416	SCCLEKAXXRHA10475	SCCLEKAX5RHB10533	SCCLEKAX2RHB10599
SCCLEKAX3RHB10417	SCCLEKAX1RHA10476	SCCLEKAXXRHA10542	SCCLEKAX5RHB10600
SCCLEKAX9RHA10418	SCCLEKAX2RHA10485	SCCLEKAX8RHB10543	SCCLEKAX0RHA10601
SCCLEKAX0RHA10419	SCCLEKAX0RHB10486	SCCLEKAX3RHA10544	SCCLEKAX2RHA10602
SCCLEKAX2RHB10425	SCCLEKAX6RHA10487	SCCLEKAX1RHB10545	SCCLEKAX4RHA10603
SCCLEKAX4RHB10426	SCCLEKAX8RHA10488	SCCLEKAX7RHA10546	SCCLEKAX6RHA10604
SCCLEKAX1RHA10428	SCCLEKAXXRHA10489	SCCLEKAX9RHA10547	SCCLEKAX4RHB10605
SCCLEKAX3RHA10429	SCCLEKAX6RHA10490	SCCLEKAX7RHB10548	SCCLEKAXXRHA10606
SCCLEKAX6RHB10430	SCCLEKAX4RHB10491	SCCLEKAX9RHB10549	SCCLEKAX1RHA10607
SCCLEKAX8RHB10431	SCCLEKAX6RHB10492	SCCLEKAX9RHA10550	SCCLEKAXXRHB10608
SCCLEKAX3RHA10432	SCCLEKAX8RHB10493	SCCLEKAX7RHB10551	SCCLEKAX5RHA10609
SCCLEKAX1RHB10433	SCCLEKAXXRHB10494	SCCLEKAX9RHB10552	SCCLEKAX4RHA10617
SCCLEKAX3RHB10434	SCCLEKAX5RHA10495	SCCLEKAXXRHB10561	SCCLEKAX2RHB10618
SCCLEKAX5RHB10435	SCCLEKAX7RHA10496	SCCLEKAX1RHB10562	SCCLEKAX4RHB10619
SCCLEKAX1RHB10447	SCCLEKAX9RHB10504	SCCLEKAX7RHA10563	SCCLEKAX0RHB10620
SCCLEKAX7RHA10448	SCCLEKAX0RHB10505	SCCLEKAX9RHA10564	SCCLEKAX2RHB10621
SCCLEKAX9RHA10449	SCCLEKAX2RHB10506	SCCLEKAX0RHA10565	SCCLEKAX8RHA10622
SCCLEKAX5RHA10450	SCCLEKAX8RHA10507	SCCLEKAX9RHB10566	SCCLEKAX6RHB10623
SCCLEKAX3RHB10451	SCCLEKAX6RHB10508	SCCLEKAX4RHA10567	SCCLEKAX1RHA10624
SCCLEKAX9RHA10452	SCCLEKAX8RHB10509	SCCLEKAX2RHB10568	SCCLEKAX3RHA10625
SCCLEKAX0RHA10453	SCCLEKAX8RHA10510	SCCLEKAX8RHA10569	SCCLEKAX5RHA10626
SCCLEKAX2RHA10454	SCCLEKAXXRHA10511	SCCLEKAX0RHB10570	SCCLEKAX3RHB10627
SCCLEKAX0RHB10455	SCCLEKAX1RHA10512	SCCLEKAX6RHA10571	SCCLEKAX4RHA10634
SCCLEKAX6RHA10456	SCCLEKAX3RHA10513	SCCLEKAX8RHA10572	SCCLEKAX4RHB10636



VINS AFFECTED BY TSB-131-24003

SCCLEKAXXRHA10637	SCCLEKAX8RHB10820	SCCLEKAX0RHB10861	SCCLEKAX6RHB10900
SCCLEKAX1RHA10638	SCCLEKAXXRHB10821	SCCLEKAX6RHA10862	SCCLEKAX1RHA10901
SCCLEKAXXRHB10639	SCCLEKAX1RHB10822	SCCLEKAXXRHA10864	SCCLEKAXXRHB10902
SCCLEKAXXRHA10640	SCCLEKAX3RHB10823	SCCLEKAX8RHB10865	SCCLEKAX5RHA10903
SCCLEKAX1RHA10641	SCCLEKAX9RHA10824	SCCLEKAXXRHB10866	SCCLEKAX3RHB10904
SCCLEKAX3RHA10642	SCCLEKAX0RHA10825	SCCLEKAX5RHA10867	SCCLEKAX5RHB10905
SCCLEKAX5RHA10643	SCCLEKAX9RHB10826	SCCLEKAX3RHB10868	SCCLEKAX0RHA10906
SCCLEKAX7RHA10644	SCCLEKAX0RHB10827	SCCLEKAX9RHA10869	SCCLEKAX9RHB10907
SCCLEKAX5RHB10645	SCCLEKAX6RHA10828	SCCLEKAX1RHB10870	SCCLEKAX4RHA10908
SCCLEKAX0RHA10646	SCCLEKAX8RHA10829	SCCLEKAX7RHA10871	SCCLEKAX2RHB10909
SCCLEKAX6RHB10654	SCCLEKAX4RHA10830	SCCLEKAX9RHA10872	SCCLEKAX9RHB10910
SCCLEKAX7RHB10680	SCCLEKAX6RHA10831	SCCLEKAX9RHB10874	SCCLEKAX0RHB10911
SCCLEKAX1RHB10691	SCCLEKAX8RHA10832	SCCLEKAX4RHA10875	SCCLEKAX6RHA10912
SCCLEKAX7RHA10692	SCCLEKAXXRHA10833	SCCLEKAX2RHB10876	SCCLEKAX4RHB10913
SCCLEKAX5RHB10693	SCCLEKAX1RHA10834	SCCLEKAX4RHB10877	SCCLEKAX6RHB10914
SCCLEKAX0RHA10694	SCCLEKAX3RHA10835	SCCLEKAXXRHA10878	SCCLEKAX1RHA10915
SCCLEKAX4RHB10801	SCCLEKAX1RHB10836	SCCLEKAX1RHA10879	SCCLEKAXXRHB10916
SCCLEKAX6RHB10802	SCCLEKAX7RHA10837	SCCLEKAX8RHA10880	SCCLEKAX5RHA10917
SCCLEKAX1RHA10803	SCCLEKAX9RHA10838	SCCLEKAXXRHA10881	SCCLEKAX3RHB10918
SCCLEKAX3RHA10804	SCCLEKAX0RHA10839	SCCLEKAX8RHB10882	SCCLEKAX5RHB10919
SCCLEKAX5RHA10805	SCCLEKAX3RHB10840	SCCLEKAXXRHB10883	SCCLEKAX5RHA10920
SCCLEKAX7RHA10806	SCCLEKAX5RHB10841	SCCLEKAX9RHA10886	SCCLEKAX7RHA10921
SCCLEKAX5RHB10807	SCCLEKAX7RHB10842	SCCLEKAX7RHB10887	SCCLEKAX9RHA10922
SCCLEKAX0RHA10808	SCCLEKAX9RHB10843	SCCLEKAX9RHB10888	SCCLEKAX7RHB10923
SCCLEKAX2RHA10809	SCCLEKAX0RHB10844	SCCLEKAX4RHA10889	SCCLEKAX9RHB10924
SCCLEKAX9RHA10810	SCCLEKAX8RHB10848	SCCLEKAX7RHB10890	SCCLEKAX4RHA10925
SCCLEKAX7RHB10811	SCCLEKAX3RHA10849	SCCLEKAX9RHB10891	SCCLEKAX6RHA10926
SCCLEKAX9RHB10812	SCCLEKAX6RHB10850	SCCLEKAX4RHA10892	SCCLEKAX4RHB10927
SCCLEKAX0RHB10813	SCCLEKAX7RHA10854	SCCLEKAX6RHA10893	SCCLEKAX6RHB10928
SCCLEKAX2RHB10814	SCCLEKAX9RHA10855	SCCLEKAX4RHB10894	SCCLEKAX1RHA10929
SCCLEKAX4RHB10815	SCCLEKAX7RHB10856	SCCLEKAXXRHA10895	SCCLEKAX4RHB10930
SCCLEKAX6RHB10816	SCCLEKAX9RHB10857	SCCLEKAX1RHA10896	SCCLEKAX3RHB10935
SCCLEKAX8RHB10817	SCCLEKAX0RHB10858	SCCLEKAXXRHB10897	SCCLEKAX5RHB10936
SCCLEKAXXRHB10818	SCCLEKAX6RHA10859	SCCLEKAX1RHB10898	SCCLEKAX0RHA10937
SCCLEKAX1RHB10819	SCCLEKAX9RHB10860	SCCLEKAX7RHA10899	SCCLEKAX9RHB10938



VINS AFFECTED BY TSB-131-24003

SCCLEKAX0RHB10939	SCCLEKAX0RHB11024	SCCLEKAX6RHB11108	SCCLEKAX5RHB11147
SCCLEKAX7RHB10940	SCCLEKAX8RHA11026	SCCLEKAX8RHB11109	SCCLEKAX7RHB11148
SCCLEKAX2RHA10941	SCCLEKAX2RHA11040	SCCLEKAX8RHA11110	SCCLEKAX9RHB11149
SCCLEKAX4RHA10942	SCCLEKAX4RHA11041	SCCLEKAXXRHA11111	SCCLEKAX5RHB11150
SCCLEKAX2RHB10943	SCCLEKAX2RHB11042	SCCLEKAX1RHA11112	SCCLEKAX7RHB11151
SCCLEKAX8RHA10944	SCCLEKAX4RHB11043	SCCLEKAX3RHA11113	SCCLEKAX9RHB11152
SCCLEKAXXRHA10945	SCCLEKAX6RHB11044	SCCLEKAX1RHB11114	SCCLEKAX0RHB11153
SCCLEKAX8RHB10946	SCCLEKAX1RHA11045	SCCLEKAX7RHA11115	SCCLEKAX2RHB11154
SCCLEKAXXRHB10947	SCCLEKAX6RHC11046	SCCLEKAX5RHB11116	SCCLEKAX8RHA11155
SCCLEKAX5RHA10948	SCCLEKAX1RHB11047	SCCLEKAX0RHA11117	SCCLEKAXXRHA11156
SCCLEKAX7RHA10949	SCCLEKAX7RHA11048	SCCLEKAX9RHB11118	SCCLEKAX8RHB11157
SCCLEKAX3RHA10950	SCCLEKAX5RHB11049	SCCLEKAX0RHB11119	SCCLEKAXXRHB11158
SCCLEKAX5RHA10951	SCCLEKAX5RHA11050	SCCLEKAX0RHA11120	SCCLEKAX1RHB11159
SCCLEKAX7RHA10952	SCCLEKAX7RHA11051	SCCLEKAX2RHA11121	SCCLEKAX8RHB11160
SCCLEKAX9RHA10953	SCCLEKAX8RHA11057	SCCLEKAX4RHA11122	SCCLEKAXXRHB11161
SCCLEKAX0RHA10954	SCCLEKAX6RHB11058	SCCLEKAX2RHB11123	SCCLEKAX5RHA11162
SCCLEKAX9RHB10955	SCCLEKAX8RHB11059	SCCLEKAX4RHB11124	SCCLEKAX7RHA11163
SCCLEKAX2RHB10960	SCCLEKAX4RHB11060	SCCLEKAXXRHA11125	SCCLEKAX9RHA11164
SCCLEKAX6RHB10962	SCCLEKAX6RHB11061	SCCLEKAX8RHB11126	SCCLEKAX0RHA11165
SCCLEKAX8RHB10963	SCCLEKAX1RHA11062	SCCLEKAX3RHA11127	SCCLEKAX9RHB11166
SCCLEKAXXRHB10964	SCCLEKAXXRHB11063	SCCLEKAX7RHA11132	SCCLEKAX4RHA11167
SCCLEKAX1RHB10965	SCCLEKAX1RHB11064	SCCLEKAX5RHB11133	SCCLEKAX2RHB11168
SCCLEKAX9RHA10967	SCCLEKAX7RHA11065	SCCLEKAX7RHB11134	SCCLEKAX8RHA11169
SCCLEKAX0RHA10968	SCCLEKAX9RHA11066	SCCLEKAX2RHA11135	SCCLEKAX0RHB11170
SCCLEKAX9RHB10969	SCCLEKAX7RHB11067	SCCLEKAX4RHA11136	SCCLEKAX6RHA11171
SCCLEKAX5RHB10970	SCCLEKAX9RHB11068	SCCLEKAX6RHA11137	SCCLEKAX8RHA11172
SCCLEKAX7RHB10971	SCCLEKAX0RHB11069	SCCLEKAX8RHA11138	SCCLEKAXXRHA11173
SCCLEKAX5RHA11016	SCCLEKAX0RHA11070	SCCLEKAXXRHA11139	SCCLEKAX1RHA11174
SCCLEKAX7RHA11017	SCCLEKAX9RHB11071	SCCLEKAX2RHB11140	SCCLEKAX3RHA11175
SCCLEKAX5RHB11018	SCCLEKAX4RHA11072	SCCLEKAX8RHA11141	SCCLEKAX1RHB11176
SCCLEKAX7RHB11019	SCCLEKAX6RHA11073	SCCLEKAX6RHB11142	SCCLEKAX7RHA11177
SCCLEKAX3RHB11020	SCCLEKAX4RHB11074	SCCLEKAX1RHA11143	SCCLEKAX5RHB11178
SCCLEKAX9RHA11021	SCCLEKAX6RHB11075	SCCLEKAX3RHA11144	SCCLEKAX0RHA11179
SCCLEKAX0RHA11022	SCCLEKAX1RHA11076	SCCLEKAX5RHA11145	SCCLEKAX3RHB11180
SCCLEKAX9RHB11023	SCCLEKAX8RHA11107	SCCLEKAX7RHA11146	SCCLEKAX5RHB11181





VINS AFFECTED BY TSB-131-24003

SCCLEKAX0RHA11182	SCCLEKAX4RHA11217	SCCLEKAX2RHB11266	SCCLEKAX4RHA11301
SCCLEKAX9RHB11183	SCCLEKAX2RHB11218	SCCLEKAX8RHA11267	SCCLEKAX6RHA11302
SCCLEKAX0RHB11184	SCCLEKAX8RHA11219	SCCLEKAXXRHA11268	SCCLEKAX8RHA11303
SCCLEKAX2RHB11185	SCCLEKAX4RHA11220	SCCLEKAX8RHB11269	SCCLEKAX6RHB11304
SCCLEKAX8RHA11186	SCCLEKAX6RHA11221	SCCLEKAX4RHB11270	SCCLEKAX1RHA11305
SCCLEKAX6RHB11187	SCCLEKAX4RHB11222	SCCLEKAXXRHA11271	SCCLEKAXXRHB11306
SCCLEKAX8RHB11188	SCCLEKAXXRHA11223	SCCLEKAX1RHA11272	SCCLEKAX5RHA11307
SCCLEKAX3RHA11189	SCCLEKAX1RHA11224	SCCLEKAX3RHA11273	SCCLEKAX3RHB11308
SCCLEKAXXRHA11190	SCCLEKAX3RHA11225	SCCLEKAX1RHB11274	SCCLEKAX9RHA11309
SCCLEKAX8RHB11191	SCCLEKAX5RHA11226	SCCLEKAX7RHA11275	SCCLEKAX1RHB11310
SCCLEKAX3RHA11192	SCCLEKAX7RHA11227	SCCLEKAX5RHB11276	SCCLEKAX7RHA11311
SCCLEKAX5RHA11193	SCCLEKAX9RHA11228	SCCLEKAX0RHA11277	SCCLEKAX9RHA11312
SCCLEKAX7RHA11194	SCCLEKAX0RHA11229	SCCLEKAX9RHB11278	SCCLEKAX7RHB11313
SCCLEKAX9RHA11195	SCCLEKAX3RHB11230	SCCLEKAX0RHB11279	SCCLEKAX9RHB11314
SCCLEKAX0RHA11196	SCCLEKAX9RHA11231	SCCLEKAX7RHB11280	SCCLEKAX4RHA11315
SCCLEKAX2RHA11197	SCCLEKAX0RHA11232	SCCLEKAX9RHB11281	SCCLEKAX2RHB11316
SCCLEKAX4RHA11198	SCCLEKAX2RHA11233	SCCLEKAX4RHA11282	SCCLEKAX8RHA11317
SCCLEKAX2RHB11199	SCCLEKAX4RHA11234	SCCLEKAX6RHA11283	SCCLEKAX6RHB11318
SCCLEKAX5RHB11200	SCCLEKAX6RHA11235	SCCLEKAX8RHA11284	SCCLEKAX1RHA11319
SCCLEKAX0RHA11201	SCCLEKAX4RHB11236	SCCLEKAXXRHA11285	SCCLEKAX4RHB11320
SCCLEKAX2RHA11202	SCCLEKAXXRHA11237	SCCLEKAX8RHB11286	SCCLEKAX6RHB11321
SCCLEKAX0RHB11203	SCCLEKAX1RHA11238	SCCLEKAX3RHA11287	SCCLEKAX8RHB11322
SCCLEKAX6RHA11204	SCCLEKAX3RHA11239	SCCLEKAX1RHB11288	SCCLEKAX3RHA11323
SCCLEKAX4RHB11205	SCCLEKAXXRHA11240	SCCLEKAX7RHA11289	SCCLEKAX5RHA11324
SCCLEKAX6RHB11206	SCCLEKAX8RHB11241	SCCLEKAX3RHA11290	SCCLEKAX3RHB11325
SCCLEKAX1RHA11207	SCCLEKAXXRHB11242	SCCLEKAX5RHA11291	SCCLEKAX5RHB11326
SCCLEKAXXRHB11208	SCCLEKAX1RHB11243	SCCLEKAX3RHB11292	SCCLEKAX0RHA11327
SCCLEKAX1RHB11209	SCCLEKAX3RHB11244	SCCLEKAX5RHB11293	SCCLEKAX9RHB11328
SCCLEKAX8RHB11210	SCCLEKAX5RHB11245	SCCLEKAX0RHA11294	SCCLEKAX4RHA11329
SCCLEKAX3RHA11211	SCCLEKAX0RHA11246	SCCLEKAX2RHA11295	SCCLEKAX7RHB11330
SCCLEKAX5RHA11212	SCCLEKAX9RHB11247	SCCLEKAX0RHB11296	SCCLEKAX2RHA11331
SCCLEKAX3RHB11213	SCCLEKAX4RHA11248	SCCLEKAX6RHA11297	SCCLEKAX0RHB11332
SCCLEKAX5RHB11214	SCCLEKAX6RHA11249	SCCLEKAX4RHB11298	SCCLEKAX2RHB11333
SCCLEKAX7RHB11215	SCCLEKAX9RHB11250	SCCLEKAX6RHB11299	SCCLEKAX8RHA11334
SCCLEKAX9RHB11216	SCCLEKAX4RHA11265	SCCLEKAX9RHB11300	SCCLEKAX6RHB11335



VINS AFFECTED BY TSB-131-24003

SCCLEKAX1RHA11336	SCCLEKAX4RHC11398	SCCLEKAX2RHD11449	SCCLEKAX1RHB11484
SCCLEKAXXRHB11337	SCCLEKAX7RHD11415	SCCLEKAX2RHC11450	SCCLEKAX7RHA11485
SCCLEKAX5RHA11338	SCCLEKAX9RHD11416	SCCLEKAX4RHC11451	SCCLEKAX9RHA11486
SCCLEKAX3RHB11339	SCCLEKAX0RHD11417	SCCLEKAX6RHC11452	SCCLEKAX0RHA11487
SCCLEKAX3RHA11340	SCCLEKAX6RHC11418	SCCLEKAX4RHD11453	SCCLEKAX2RHA11488
SCCLEKAX5RHA11341	SCCLEKAX4RHD11419	SCCLEKAX6RHD11454	SCCLEKAX0RHB11489
SCCLEKAX3RHB11342	SCCLEKAX4RHC11420	SCCLEKAX8RHD11455	SCCLEKAX0RHA11490
SCCLEKAX5RHB11343	SCCLEKAX6RHC11421	SCCLEKAXXRHD11456	SCCLEKAX2RHA11491
SCCLEKAX7RHB11344	SCCLEKAX8RHC11422	SCCLEKAX5RHC11457	SCCLEKAX0RHB11492
SCCLEKAX9RHB11345	SCCLEKAX6RHD11423	SCCLEKAX3RHD11458	SCCLEKAX2RHB11493
SCCLEKAX0RHB11346	SCCLEKAX8RHD11424	SCCLEKAX9RHC11459	SCCLEKAX4RHB11494
SCCLEKAX2RHB11347	SCCLEKAXXRHD11425	SCCLEKAX1RHD11460	SCCLEKAX6RHB11495
SCCLEKAX8RHA11348	SCCLEKAX1RHD11426	SCCLEKAX7RHC11461	SCCLEKAX1RHA11496
SCCLEKAX1RHC11360	SCCLEKAX7RHC11427	SCCLEKAX9RHC11462	SCCLEKAXXRHB11497
SCCLEKAX3RHC11361	SCCLEKAX5RHD11428	SCCLEKAX0RHC11463	SCCLEKAX5RHA11498
SCCLEKAX5RHC11362	SCCLEKAX0RHC11429	SCCLEKAX9RHD11464	SCCLEKAXXRHA11500
SCCLEKAX7RHC11363	SCCLEKAX7RHC11430	SCCLEKAX0RHD11465	SCCLEKAX8RHB11501
SCCLEKAX9RHC11364	SCCLEKAX9RHC11431	SCCLEKAX6RHC11466	SCCLEKAX3RHA11502
SCCLEKAX0RHC11365	SCCLEKAX0RHC11432	SCCLEKAX8RHC11467	SCCLEKAX1RHB11503
SCCLEKAX2RHC11366	SCCLEKAX2RHC11433	SCCLEKAXXRHC11468	SCCLEKAX3RHB11504
SCCLEKAX4RHC11367	SCCLEKAX0RHD11434	SCCLEKAX8RHD11469	SCCLEKAX7RHA11505
SCCLEKAX2RHD11368	SCCLEKAX6RHC11435	SCCLEKAX8RHC11470	SCCLEKAX7RHB11506
SCCLEKAX8RHC11369	SCCLEKAX8RHC11436	SCCLEKAX6RHD11471	SCCLEKAX2RHA11507
SCCLEKAX0RHD11370	SCCLEKAXXRHC11437	SCCLEKAX8RHD11472	SCCLEKAX0RHB11508
SCCLEKAX2RHD11371	SCCLEKAX1RHC11438	SCCLEKAXXRHD11473	SCCLEKAX2RHB11509
SCCLEKAX8RHC11372	SCCLEKAX3RHC11439	SCCLEKAX5RHC11474	SCCLEKAX2RHA11510
SCCLEKAXXRHC11373	SCCLEKAXXRHC11440	SCCLEKAX3RHD11475	SCCLEKAX0RHB11511
SCCLEKAX8RHD11374	SCCLEKAX8RHD11441	SCCLEKAX2RHB11476	SCCLEKAX6RHA11512
SCCLEKAX6RHD11387	SCCLEKAXXRHD11442	SCCLEKAX8RHA11477	SCCLEKAX4RHB11513
SCCLEKAX1RHC11388	SCCLEKAX5RHC11443	SCCLEKAX6RHB11478	SCCLEKAXXRHA11514
SCCLEKAX3RHC11389	SCCLEKAX7RHC11444	SCCLEKAX1RHA11479	SCCLEKAX8RHB11515
SCCLEKAX6RHD11390	SCCLEKAX5RHD11445	SCCLEKAX4RHB11480	SCCLEKAXXRHB11516
SCCLEKAX8RHD11391	SCCLEKAX0RHC11446	SCCLEKAXXRHA11481	SCCLEKAX5RHA11517
SCCLEKAX3RHC11392	SCCLEKAX2RHC11447	SCCLEKAX1RHA11482	SCCLEKAX3RHB11518
SCCLEKAX2RHC11397	SCCLEKAX0RHD11448	SCCLEKAX3RHA11483	SCCLEKAX9RHA11519





VINS AFFECTED BY TSB-131-24003

SCCLEKAX5RHA11520	SCCLEKAX4RHB11558	SCCLEKAX1RHB11601	SCCLEKAX1RHA11644
SCCLEKAX3RHB11521	SCCLEKAX6RHB11559	SCCLEKAX3RHB11602	SCCLEKAX3RHA11645
SCCLEKAX5RHB11522	SCCLEKAX6RHA11560	SCCLEKAX9RHA11603	SCCLEKAX5RHA11646
SCCLEKAX0RHA11523	SCCLEKAX4RHB11561	SCCLEKAX7RHB11604	SCCLEKAX3RHB11647
SCCLEKAX2RHA11524	SCCLEKAX6RHB11562	SCCLEKAX2RHA11605	SCCLEKAXXRHA11657
SCCLEKAX4RHA11525	SCCLEKAX1RHA11563	SCCLEKAX4RHA11606	SCCLEKAX1RHA11658
SCCLEKAX6RHA11526	SCCLEKAX7RHA11566	SCCLEKAX2RHB11607	SCCLEKAX3RHA11659
SCCLEKAX8RHA11527	SCCLEKAX9RHA11567	SCCLEKAX4RHB11608	SCCLEKAX6RHB11660
SCCLEKAXXRHA11528	SCCLEKAX7RHB11568	SCCLEKAXXRHA11609	SCCLEKAX8RHB11661
SCCLEKAX8RHB11529	SCCLEKAX9RHB11569	SCCLEKAX2RHB11610	SCCLEKAX3RHA11662
SCCLEKAX8RHA11530	SCCLEKAX5RHB11570	SCCLEKAX4RHB11611	SCCLEKAX5RHA11663
SCCLEKAX6RHB11531	SCCLEKAX0RHA11571	SCCLEKAXXRHA11612	SCCLEKAX3RHB11664
SCCLEKAX1RHA11532	SCCLEKAX9RHB11572	SCCLEKAX8RHB11613	SCCLEKAX5RHB11665
SCCLEKAX3RHA11533	SCCLEKAX0RHB11573	SCCLEKAXXRHB11614	SCCLEKAX7RHB11666
SCCLEKAX1RHB11534	SCCLEKAX6RHA11574	SCCLEKAX1RHB11615	SCCLEKAX9RHB11667
SCCLEKAX3RHB11535	SCCLEKAX8RHA11575	SCCLEKAX2RHB11624	SCCLEKAX0RHB11668
SCCLEKAX5RHB11536	SCCLEKAX6RHB11576	SCCLEKAX4RHB11625	SCCLEKAX6RHA11669
SCCLEKAX4RHA11539	SCCLEKAX8RHB11577	SCCLEKAXXRHA11626	SCCLEKAX9RHB11670
SCCLEKAX0RHA11540	SCCLEKAX3RHA11578	SCCLEKAX1RHA11627	SCCLEKAX4RHA11671
SCCLEKAX9RHB11541	SCCLEKAX5RHA11579	SCCLEKAXXRHB11628	SCCLEKAX2RHB11672
SCCLEKAX0RHB11542	SCCLEKAX8RHB11580	SCCLEKAX1RHB11629	SCCLEKAX8RHA11673
SCCLEKAX2RHB11543	SCCLEKAX3RHA11581	SCCLEKAX1RHA11630	SCCLEKAX6RHB11674
SCCLEKAXXRHA11545	SCCLEKAX1RHB11582	SCCLEKAXXRHB11631	SCCLEKAX1RHA11675
SCCLEKAX1RHA11546	SCCLEKAX3RHB11583	SCCLEKAX5RHA11632	SCCLEKAX3RHA11676
SCCLEKAX3RHA11547	SCCLEKAX5RHB11584	SCCLEKAX3RHB11633	SCCLEKAX5RHA11677
SCCLEKAX1RHB11548	SCCLEKAX7RHB11585	SCCLEKAX9RHA11634	SCCLEKAX3RHB11678
SCCLEKAX7RHA11549	SCCLEKAX2RHA11586	SCCLEKAX7RHB11635	SCCLEKAX5RHB11679
SCCLEKAXXRHB11550	SCCLEKAX0RHB11587	SCCLEKAX9RHB11636	SCCLEKAX5RHA11680
SCCLEKAX1RHB11551	SCCLEKAX2RHB11588	SCCLEKAX0RHB11637	SCCLEKAX7RHA11681
SCCLEKAX7RHA11552	SCCLEKAX8RHA11589	SCCLEKAX6RHA11638	SCCLEKAX9RHA11682
SCCLEKAX5RHB11553	SCCLEKAX1RHB11596	SCCLEKAX4RHB11639	SCCLEKAX0RHA11683
SCCLEKAX0RHA11554	SCCLEKAX7RHA11597	SCCLEKAX4RHA11640	SCCLEKAX2RHA11684
SCCLEKAX9RHB11555	SCCLEKAX9RHA11598	SCCLEKAX2RHB11641	SCCLEKAX4RHA11685
SCCLEKAX4RHA11556	SCCLEKAX7RHB11599	SCCLEKAX4RHB11642	SCCLEKAX6RHA11686
SCCLEKAX2RHB11557	SCCLEKAX3RHA11600	SCCLEKAX6RHB11643	SCCLEKAX4RHB11687



VINS AFFECTED BY TSB-131-24003

SCCLEKAXXRHA11688	SCCLEKAX4RHA11735	SCCLEKAX9RHB11782	SCCLEKAX1RHC11827
SCCLEKAX8RHB11689	SCCLEKAX2RHB11736	SCCLEKAX4RHA11783	SCCLEKAX3RHC11828
SCCLEKAX4RHB11690	SCCLEKAX8RHA11737	SCCLEKAX6RHA11784	SCCLEKAX5RHC11829
SCCLEKAXXRHA11691	SCCLEKAXXRHA11738	SCCLEKAX4RHB11785	SCCLEKAX1RHC11830
SCCLEKAX1RHA11692	SCCLEKAX1RHA11739	SCCLEKAX6RHB11786	SCCLEKAX2RHD11838
SCCLEKAX3RHA11693	SCCLEKAX4RHB11740	SCCLEKAX1RHA11787	SCCLEKAX8RHC11839
SCCLEKAX1RHB11694	SCCLEKAX6RHB11741	SCCLEKAXXRHB11788	SCCLEKAX4RHC11840
SCCLEKAX7RHA11695	SCCLEKAX5RHB11746	SCCLEKAX1RHB11789	SCCLEKAX4RHD11842
SCCLEKAX5RHB11701	SCCLEKAX7RHB11747	SCCLEKAX8RHB11790	SCCLEKAXXRHC11843
SCCLEKAX7RHB11702	SCCLEKAX9RHB11748	SCCLEKAXXRHB11791	SCCLEKAX8RHD11844
SCCLEKAX2RHA11703	SCCLEKAXXRHB11757	SCCLEKAX1RHB11792	SCCLEKAXXRHD11845
SCCLEKAX4RHA11704	SCCLEKAX5RHA11758	SCCLEKAX3RHB11793	SCCLEKAX1RHD11846
SCCLEKAX6RHA11705	SCCLEKAX3RHB11759	SCCLEKAX5RHB11794	SCCLEKAX7RHC11847
SCCLEKAX5RHA11713	SCCLEKAXXRHB11760	SCCLEKAX0RHA11795	SCCLEKAX5RHD11848
SCCLEKAX7RHA11714	SCCLEKAX1RHB11761	SCCLEKAX2RHA11796	SCCLEKAX7RHD11849
SCCLEKAX9RHA11715	SCCLEKAX3RHB11762	SCCLEKAX4RHA11797	SCCLEKAX7RHC11850
SCCLEKAX7RHB11716	SCCLEKAX9RHA11763	SCCLEKAXXRHB11807	SCCLEKAX9RHC11851
SCCLEKAX2RHA11717	SCCLEKAX0RHA11764	SCCLEKAX1RHB11808	SCCLEKAXXRHC11860
SCCLEKAX4RHA11718	SCCLEKAX2RHA11765	SCCLEKAX7RHA11809	SCCLEKAX1RHC11861
SCCLEKAX2RHB11719	SCCLEKAX4RHA11766	SCCLEKAX6RHC11810	SCCLEKAX3RHC11862
SCCLEKAX9RHB11720	SCCLEKAX6RHA11767	SCCLEKAX4RHD11811	SCCLEKAX1RHD11863
SCCLEKAX0RHB11721	SCCLEKAX8RHA11768	SCCLEKAXXRHC11812	SCCLEKAX3RHD11864
SCCLEKAX6RHA11722	SCCLEKAXXRHA11769	SCCLEKAX8RHD11813	SCCLEKAX9RHC11865
SCCLEKAX4RHB11723	SCCLEKAX2RHB11770	SCCLEKAX3RHC11814	SCCLEKAX7RHD11866
SCCLEKAX6RHB11724	SCCLEKAX4RHB11771	SCCLEKAX5RHC11815	SCCLEKAX2RHC11867
SCCLEKAX1RHA11725	SCCLEKAXXRHA11772	SCCLEKAX3RHD11816	SCCLEKAX0RHD11868
SCCLEKAX3RHA11726	SCCLEKAX1RHA11773	SCCLEKAX5RHD11817	SCCLEKAX2RHD11869
SCCLEKAX5RHA11727	SCCLEKAX3RHA11774	SCCLEKAX0RHC11818	SCCLEKAX2RHC11870
SCCLEKAX7RHA11728	SCCLEKAX5RHA11775	SCCLEKAX9RHD11819	SCCLEKAX8RHB11871
SCCLEKAX5RHB11729	SCCLEKAX7RHA11776	SCCLEKAX7RHD11821	SCCLEKAX3RHA11872
SCCLEKAX1RHB11730	SCCLEKAX9RHA11777	SCCLEKAX2RHC11822	SCCLEKAX5RHA11873
SCCLEKAX3RHB11731	SCCLEKAX0RHA11778	SCCLEKAX4RHC11823	SCCLEKAX7RHA11874
SCCLEKAX9RHA11732	SCCLEKAX2RHA11779	SCCLEKAX6RHC11824	SCCLEKAX9RHA11875
SCCLEKAX0RHA11733	SCCLEKAX9RHA11780	SCCLEKAX4RHD11825	SCCLEKAX7RHB11876
SCCLEKAX9RHB11734	SCCLEKAX0RHA11781	SCCLEKAXXRHC11826	SCCLEKAX9RHB11877



## VINS AFFECTED BY TSB-131-24003

SCCLEKAX0RHB11878	SCCLEKAX9RHB11913
SCCLEKAX6RHA11879	SCCLEKAX0RHB11914
SCCLEKAX9RHB11880	SCCLEKAX2RHB11915
SCCLEKAX0RHB11881	SCCLEKAX4RHB11916
SCCLEKAX2RHB11882	SCCLEKAXXRHA11917
SCCLEKAX8RHA11883	SCCLEKAX8RHB11918
SCCLEKAX6RHB11884	SCCLEKAXXRHB11919
SCCLEKAX1RHA11885	SCCLEKAX6RHB11920
SCCLEKAXXRHB11886	SCCLEKAX8RHB11921
SCCLEKAX5RHA11887	SCCLEKAXXRHB11922
SCCLEKAX3RHB11888	SCCLEKAX1RHB11923
SCCLEKAX5RHB11889	SCCLEKAX7RHA11924
SCCLEKAX5RHA11890	SCCLEKAX5RHB11925
SCCLEKAX7RHA11891	SCCLEKAX7RHB11926
SCCLEKAX9RHA11892	SCCLEKAX2RHA11927
SCCLEKAX0RHA11893	SCCLEKAX4RHA11928
SCCLEKAX2RHA11894	SCCLEKAX2RHB11929
SCCLEKAX0RHB11895	SCCLEKAX9RHB11930
SCCLEKAX2RHB11896	SCCLEKAX4RHA11931
SCCLEKAX8RHA11897	SCCLEKAX6RHA11932
SCCLEKAX6RHB11898	SCCLEKAX4RHB11933
SCCLEKAX1RHA11899	SCCLEKAXXRHA11934
SCCLEKAX0RHB11900	SCCLEKAX8RHB11935
SCCLEKAX2RHB11901	SCCLEKAXXRHB11936
SCCLEKAX8RHA11902	SCCLEKAX1RHB11937
SCCLEKAX6RHB11903	SCCLEKAX3RHB11938
SCCLEKAX8RHB11904	SCCLEKAX9RHA11939
SCCLEKAXXRHB11905	SCCLEKAX8RHA11947
SCCLEKAX5RHA11906	SCCLEKAX6RHB11948
SCCLEKAX7RHA11907	SCCLEKAX8RHB11949
SCCLEKAX5RHB11908	SCCLEKAX4RHB11950
SCCLEKAX7RHB11909	SCCLEKAX6RHB11951
SCCLEKAX7RHA11910	SCCLEKAX8RHB11952
SCCLEKAX9RHA11911	SCCLEKAX3RHA11953
SCCLEKAX0RHA11912	